One **Site Review Date:** 

Willmar, MN Rice Memorial Hospital

**GPS ID:** G Airspace: Weather:

KBDH -113.7 **Radio Preset:** \_nm Nearest Aprt: KBDH (G) **Heading/Dist:** lbs **VORTAC**: ETE / Fuel: mins/ BDH 084°/3.4

Comm/Flight Following/Medical Support

**Pad Information Lighting** 

PCL: Surface / Elev: Rooftop / 1179 No *TLOF/FATO*: 45x45 / Beacon: Yes Max Pad Weight: lbs Perimeter: Yes Max Rotor Diam: ft Flood: Yes Security: Windsock: Lighted

### Preferred App/Dep:

#### **Obstructions / Cautions / Notes**



Willmar, MN Rice Memorial Hospital (MY44) N 45° 07.3' W 95° 02.0' IMPORTANT: The pilot retains full responsibility for safe and legal flight operations, regardless of data presented on this page.

**Site Review Date:** One

## Willmar, MN

# Rice Memorial Hospital

**Jet-A Fuel Information** 

Nearest Fuel: **KBDH** Phone:

507-235-4844

**Hospital Information** 

*Unit*:

Unit Phone: 320-235-4543 Addr: 301 Becker Av SW Willmar, MN 56201

County: Kandiyohi

**Nearest Weather Reporting** 

KBDH 113.7 320-235-8287

Frequency/PL (Wulf/Tone/Tech):

T-155.400 / PL 15 / 103.5 / 13 R-155.400 / PL 15 / 103.5 / 13


Encode: MRI:

### **Additional Notes**

4 story brick bldg, New rooftop helipad on west side of hosp







N 45° 07.3' W 95° 02.0' Willmar, MN Rice Memorial Hospital (MY44)

IMPORTANT: The pilot retains full responsibility for safe and legal flight operations, regardless of data presented on this page.